

Vehicle Pricing Matrix - Car

Action	Cost
Touch/in	£40.00
Touch/in & Flat/Polish	£50.00
Full Mop Polish and Touch/in	£90.00
Cold Metal	£42.00
Cold Metal Enhanced	£84.00
Re-align	£40.00
De-decal	Please Call
Clean	£20.00
Full Valet	£40.00
Interior Trim Repair	£63.00
Door Moulding Paint	£30.00
Painted Trim	£60.00
Local Paint	£90.00
Paint	£170.00
Local Repair/Replace	£110.00
Repair/Replace Small (1 hour repair)	£212.50
Repair/Replace Large (2 hour repair)	£255.00
Wheel/trim Repair/Replace	£10.00
Alloy Repair	£60.00
Windscreen Repair	£60.00
Window Switch/Boot Lock/Etc. (Inoperative)	£27.50

Replacement	Cost
Alloy Wheel Key	£75.00
Jack	£60.00
Key Volume	£95.00
Service Book	£40.00
Literature Pack	£40.00
Load Cover Volume	£140.00
Sat Nav Disc	£250.00
Tyre Volume	£80.00
Windscreen	Please Call

Missed Service	Cost
Service Volume - Missed 1	£175.00
Service Volume - Missed All	£550.00

Specifics for Prestige Vehicles	Cost
Tyre Prestige	£170.00
Key Prestige	£150.00
Load Cover Prestige	£230.00
Service Prestige - Missed 1	£275.00
Service Prestige - Missed All	£950.00

If you need to talk to us about possible charges, you can contact us on:
inspections@pendragon.uk.com or call 01332 287157

Vehicle Pricing Matrix – LCV/Commercial

Action	Cost
Touch/in	£40.00
Touch/in & Flat/Polish	£50.00
Full Mop Polish and Touch/in	£90.00
Cold Metal	£42.00
Cold Metal Enhanced	£84.00
Re-align	£40.00
De-decal	Please Call
Clean	£20.00
Full Valet	£40.00
Interior Trim Repair	£63.00
Door Moulding Paint	£30.00
Painted Trim	£60.00
Local Paint	£90.00
Paint	£170.00
Local Repair/Replace	£110.00
Repair/Replace Small (1 hour repair)	£212.50
Repair/Replace Large (2 hour repair)	£255.00
Wheel/trim Repair/Replace	£10.00
Alloy Repair	£60.00
Windscreen Repair	£60.00
Window Switch/Boot Lock/Etc. (Inoperative)	£27.50

Replacement	Cost
Alloy Wheel Key	£75.00
Jack	£60.00
Key Volume	£95.00
Service Book	£40.00
Literature Pack	£40.00
Load Cover Volume	£140.00
Sat Nav Disc	£250.00
Tyre Volume	£80.00
Windscreen	Please Call

LCV Specific Replace/Repair	Cost
Roof Small (LCV)	£325.00
Roof Large (LCV)	£480.00
Replace Roof LCV	£1,750.00

Missed Service	Cost
Service Volume - Missed 1	£175.00
Service Volume - Missed All	£550.00

If you need to talk to us about possible charges, you can contact us on:
inspections@pendragon.uk.com or call **01332 287157**